

Certificate of Compliance

Certificate Number(s):

UL-US-L121190-33721-
91600002-4

Report Reference:

E121190-20000619

Issue Date:

2026-05-13

Issued to:

ABB AG – STOTZ-KONTAKT
Eppelheimer Str 82., Heidelberg, 69123, DE

This certificate confirms that representative samples of:
NLRV - Motor Controllers, Manual

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

UL 60947-4-1, 3rd Ed., Issue Date: 2014-04-04, Revision Date: 2017-10-17

UL 60947-1, 5th Ed., Issue Date: 2013-07-31, Revision Date: 2019-05-06

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



David Piecuch
UL Mark Certification Program Manager



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

CERTIFICATE OF COMPLIANCE

Certificate number(s): UL-US-L121190-33721-91600002-4
Report reference: E121190-20000619
Issue Date: 2026-03-23

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Motor Controllers - Manual

Model(s): Accessories, Feeder Block, : DBM35, S1-M1-25, S1-M2-25, S1-M3-25, S1-M3-35, S3-M2, S3-M3, S2-M3-50, S3-M1, DBM32

Accessories, Feeder Bus Bar Assembly, : PS3-2-2, PS3-4-2

Model(s): Accessories, Feeder Bus Bar Assembly, : PS1 followed by -2, -3, -4, or -5, followed by -0 or -1 followed by -65, followed by K.

Model(s): Accessories, Feeder Bus Bar Assembly, : PS1 followed by -2, -3, -4, -5 or -6 followed by -0 or -1 -2 followed by -65, -100.

Model(s): Accessories, Feeder Bus Bar Assembly, : PS3 followed by -2, -3, -4, -5 or -6 followed by -0, -1 or -2.

Model(s): Accessories, Feeder Bus Bar Assembly, : PS2 followed by -2, -3, -4, or -5 followed by -0, -1 or -2 followed by -125.

Model(s): Accessories, Feeder Bus Bar Assembly, : DM32 followed by -210, -240, -207, -208, may be followed by S

Certificate of Compliance

Certificate Number(s):

UL-CA-L121190-33751-
91600002-4

Report Reference:

E121190-20000619

Issue Date:

2026-05-13

Issued to:

ABB AG – STOTZ-KONTAKT
Eppelheimer Str 82., Heidelberg, 69123, DE

This certificate confirms that representative samples of:
NLRV7 - Motor Controllers, Manual Certified for Canada

See Addendum Page for Product Designation(s).

Have been evaluated by UL in accordance with the Standard(s) indicated on this Certificate.

**CSA C22.2 NO. 60947-4-1, 2nd Ed., Issue Date: 2014-04-04,
Revised 2018-05**

CSA C22.2 No. 60947-1, 2nd Ed., Issue Date: 2013-07-01

Additional Information:

See UL Product iQ® at <https://iq.ulprospector.com> for additional information.

This Certificate of Compliance indicates that representative samples of the product described in the certification report have met the requirements for UL certification. It does not provide authorization to apply the UL Mark. Only the Authorization Page that references the Follow-Up Services Procedure for ongoing surveillance provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



David Piecuch
UL Mark Certification Program Manager



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact UL Solutions Customer Service at <https://www.ul.com/contact-us>.

CERTIFICATE OF COMPLIANCE

Certificate number(s): UL-CA-L121190-33751-91600002-4
Report reference: E121190-20000619
Issue Date: 2026-03-23

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Motor Controllers - Manual

Model(s): Accessories, Feeder Block, : DBM35, S1-M1-25, S1-M2-25, S1-M3-25, S1-M3-35, S3-M2, S3-M3, S2-M3-50, S3-M1, DBM32

Accessories, Feeder Bus Bar Assembly, : PS3-2-2, PS3-4-2

Model(s): Accessories, Feeder Bus Bar Assembly, : PS1 followed by -2, -3, -4, or -5, followed by -0 or -1 followed by -65, followed by K.

Model(s): Accessories, Feeder Bus Bar Assembly, : PS1 followed by -2, -3, -4, -5 or -6 followed by -0 or -1 -2 followed by -65, -100.

Model(s): Accessories, Feeder Bus Bar Assembly, : PS3 followed by -2, -3, -4, -5 or -6 followed by -0, -1 or -2.

Model(s): Accessories, Feeder Bus Bar Assembly, : PS2 followed by -2, -3, -4, or -5 followed by -0, -1 or -2 followed by -125.

Model(s): Accessories, Feeder Bus Bar Assembly, : DM32 followed by -210, -240, -207, -208, may be followed by S